


Niveau 1



- |  |  |   |
|--|--|---|
| 1 secondary entrance for groups                  | 13 staff entrance                      | 25 museum offices                                   |
| 2 entrance for the disabled                      | 14 staff facilities                    | 26 historical museum (19th century)                 |
| 3 ticket sale and interactive info point         | 15 museum shop and coffee corner       | 27 historical museum (19th century) - Rubens Hall   |
| 4 café/restaurant                                | 16 entrance foyer                      | 28 historical museum (19th century) - Van Dyck Hall |
| 5 kitchen  | 17 historical ticket booths            | 29 restoration atelier                              |
| 6 wardrobe lockers                               | 18 auditorium/event hall               | 30 museum atelier                                   |
| 7 library – reading room                         | 19 Keyserzaal                          | 31 new museum (21st century) - blue cabinets        |
| 8 statues depot                                  | 20 historical museum (20th century)    | 32 offices  |
| 9 depot/storage                                  | 21 entry point for extra large artwork | 33 technical installations                          |
| 10 main depot                                    | 22 new museum (21st century)           |   |
| 11 artwork elevator                              | 23 Monumental stair hall               |   |
| 12 entry point for small to medium sized artwork | 24 meeting room                        |   |

